

HRA-1500MP

VINTAGE RADIO RECEIVER WITH CD / MP3 / WMA PLAYER

STEREO SOUND

TOP LOADING CD / MP3 / WMA PLAYER

REPEAT / PROGRAM FUNCTIONS

FM/MW-BAND

MANUAL TUNING

EARPHONES OUTPUT

CD FULL FUNCTIONS REMOTE CONTROL

HRA-1500MP

audio products



MP3



VINTAGE RADIO RECEIVER WITH CD / MP3 PLAYER

- STEREO SOUND
- TOP LOADING CD PLAYER
- REPEAT / PROGRAM FUNCTIONS
- FM/MW-BAND
- MANUAL TUNING
- EARPHONES OUTPUT
- CD FULL FUNCTION REMOTE CONTROL



HRA-1500MP

CD PLAYER	Loader type	Top loading
	Audio playback	WAV (CD-DA), MP3 / WMA
	Disc support	CD-DA / CD-R / CD-RW
	Auto ID3 tag detection	-
	Anti-Schock protection	-
	MP3 search by	Track
	Data rate system	-
	Fast forward / reverse	•
	Track search	•
	Intro scan	-
	Random play	-
	Repeat track / album	• / •
TUNER	Program function	20 tracks
	Tuner type	Analogue with AFC
	Ranges (band)	FM/MW
	RDS system / Radiotext	-
	Preset stations	-
	Last tuned-in station retained	-
	Stereo / Mono selector	-
	Automatic tuning	-
	Manual tuning	•
AUDIO	Total PMPO Output Power	28 Watt
	Nominal Output Power (RMS)	2 x 1.8 Watt @ 10% THD
	Electronic volume control	-
	Bass Boost System	-
	Tone control	-
GENERAL	Speaker system	2 speakers, wideband
	Display / Illumination	-
	Keylock function	-
	Clock function	-
	Alarm function	-
	Sleep function	-
	Light illumination	Dial scale illumination
	Power supply	230V AC
	Battery power	-
	External DC power input	-
	Weight	4,65 kg
	Dimensions (WxHxD)	315 x 220 x 207 mm
	Accessories included	-
CONNECT.	Colour	Wood
	USB port	-
	Card slot	-
	RCA Aux-In	-
	Headphones socket	• (Ø 3.5 mm)
COMMERCIAL	Antenna	FM wire antenna
	Container load 40'	2'270 pcs
	Container load 20'	-
	Shipping carton	1 pc
	Gift Box size (WxHxD)	366 x 285 x 253 mm
	Shipping carton size (WxHxD)	-
	EAN code	76 21800 02842 6
	Country of origin	P.R.C.

Playability of self-made CDs on Roadstar CD drive mechanisms.

CD-R/CD-RW in CD-DA and in MP3 or WMA format can be played back. However it can occur, due to differences in the quality of the media as well as the characteristics of the recording, that individual self-made CDs cannot be read. This does not indicate an incorrect function of the playback unit in these cases.